FORKLIFT BATTERY CHARGING

TIPS FOR OPPORTUNITY AND FAST CHARGING

In industries with extended shift operations, opportunity charging is a valuable solution, eliminating the need for frequent battery changes. Not only does it prolong the runtime of aging batteries, but also restores lost capacity over time.

See our **Total Warehouse Tips** for best opportunity and fast charging for your forklift batteries.





Use breaks and shift changes of 10 minutes or more to maximize your charging time.



Keep batteries above 30% state of charge for fast charging or 20% for opportunity charging to maximize their life.



Check connections frequently to ensure they are secure. Check for damaged cables or connections that need replacement.



When charging, keep the battery compartment open to improve ventilation and cooling.



Do NOT disconnect the battery from the charger before turning off the charger first.



After a break, choose the truck with the highest state of charge.



Ensure that all batteries receive a weekly equalize charge to ensure peak performance.



Always check water levels after an equalize charge and top off as needed.



Contact Total Warehouse for battery and charger services and energy solutions.

